

**Asbestos Containing Materials Survey
And
Register
Karama Shopping Plaza**



Property Name: Karama Shopping Centre
Property Address: Kalymnos Drive Karama NT 0820
Prepared for: Peter LaPira

Prepared by: Tracy Allen
Northern Trade Solutions

Date: 27.03.2015
Number of Structures 1
Register No: NTS304
Register Version: 01

Written/Submitted by:

Tracy Allen

Licensed Assessor NTWS-AA-439630 & Asbestos Consultant NT

Northern Trade Solutions

Unit 4/51 Albatross St, Winnellie, NT, 0821
P O Box 39231, Winnellie, NT, 0821
Ph: (08)89843017 Fax: (08)89843855
Mobile: 0407 953 833
Email: tracy.allen@ntsnt.com.au
Web: www.ntsnt.com.au

Table of Contents

1.	<u>INSTRUCTIONS</u>	<u>3</u>
2.	<u>INTRODUCTION POLICIES & MANAGEMENT PROCEDURE</u>	<u>3</u>
3.	<u>REGULATORY FRAMEWORK FOR ASBESTOS MANAGEMENT</u>	<u>4</u>
4.	<u>LIMITATIONS & DEFINITIONS</u>	<u>5</u>
5.	<u>RISK EVALUATIONS</u>	<u>7</u>
6.	<u>CONCLUSIONS & RECOMMENTATIONS</u>	<u>9</u>
7.	<u>INSPECTION REPORT</u>	<u>9</u>

APPENDIX	A	CONTROL FORM
APPENDIX	B	INSPECTION DETAILS
APPENDIX	C	ASBESTOS REGISTER
APPENDIX	D	LABORATORY RESULTS
APPENDIX	E	AUDIT SUMMARY

1.0 INSTRUCTIONS

Northern Trade Solution has been requested by Peter La Pira on behalf of the Karama Shopping Plaza to compile a survey of all accessible areas within the shopping complex, i.e. all accessible areas within the complex. This report presents an update of the findings of a Hazardous Building Materials Survey for the Karama Shopping Plaza on Kalymnos Drive, Karama, NT 0820. This register has been compiled to comply with the new, **WORK HEALTH AND SAFETY (NATIONAL UNIFORM LEGISLATION REGULATIONS)** As in force at 24 December 2014 that states that; a person with management or control of a workplace must ensure that a register (an *asbestos register*) is prepared and kept at the workplace. This only applies to workplaces constructed prior to 31 Dec 2003.

2.0 INTRODUCTION POLICIES & MANAGEMENT PROCEDURE

Northern Trade Solutions have professional, competent and fully qualified staff in all matters of Asbestos management, assessment and removal, in the friable and non-friable (bonded categories). Northern Trade Solutions adhere to the strict regulatory stipulations on all matters concerning Asbestos Management, removal and the preparation and maintenance of surveys and registers. Northern Trade Solutions only utilise NATA accredited laboratories to identify the presence of materials containing Asbestos. Northern Trade Solutions will assist clients engaging with Northern Trade Solutions in the complete consultation process, assessment, control and management of all Asbestos related issues that may arise in the client's business undertakings.

It is important to note that if Asbestos products are disturbed, asbestos fibres may be released, thereby resulting in a health risk. Great care therefore must be exercised in the immediate and ongoing management of any products found to contain Asbestos

If products containing Asbestos have been identified in this building, specific actions are required as follows:

"Refer to 5.0 Risk evaluations"

Northern Trade Solutions recommend that the following management plan be prepared

- Adopt procedures that restrict access to the Asbestos containing products.
- Ensure that all parties having management responsibilities in relation to the building or site are made aware of the Asbestos Register, audit reports and risks of asbestos containing materials.
- Management must ensure all staff, contractors and sub-contractors are aware of the presence of asbestos on the site, particularly prior to work being carried out on Asbestos containing materials.
- When removal of Asbestos containing materials is required or changes to the building are required affecting Asbestos containing materials, management, staff, contractors and subcontractors must be made aware that breakage, cutting or machining of Asbestos containing materials is likely to cause Asbestos fibres to be released, resulting in an increased health and safety risk.
- Within prescribed parameters, when either friable or non-friable (bonded) materials are to be removed, NT Worksafe regulations stipulate only licensed Asbestos removal companies can remove the materials, for further information contact Northern Trade Solutions or NT Worksafe.

- In accordance with existing legislation, Asbestos registers should be updated at least every 5 years.
- In accordance with existing legislation, warning signs must be installed on Asbestos containing materials. Please contact Northern Trade Solutions regarding sign installation.
- Any person who intends to carry out work must first be shown this Asbestos register and sign the control form in appendix A.
- Vinyl tile and vinyl sheet flooring manufactured prior to 1982, in many cases contained Asbestos, it is a safe practice to therefore, in the event of renovation work or other activities disturbing such flooring, to assume that the material does in fact contain Asbestos. Laboratory testing at the time of works would verify the existence or otherwise of Asbestos. If the existence of Asbestos has been positively identified within this report then no further testing would be required.
- It was common practice until the late 1970's for small diameter hot water pipes to be concealed in walls and to be partially or totally insulated with brown or white Asbestos. Confirmation or otherwise as to the presence of these "chased" pipes is simply not possible with a non-destructive visual inspection. Appropriate precaution must be observed if the walls are disturbed in the vicinity of concealed hot water pipes.
- All work which could involve disturbing the materials containing Asbestos must be carried out in accordance to the requirements of the Code of Practice on 'HOW TO MANAGE AND CONTROL ASBESTOS IN THE WORKPLACE' and the Code of Practice on 'HOW TO SAFELY REMOVE ASBESTOS' as approved under section 274 of the WORK HEALTH SAFETY ACT (the ACT). A copy of the publications should be kept with the Asbestos register.
- In the event of further Asbestos products being located at the property, details should be immediately added to any existing asbestos register.
- A copy of the Asbestos Register must be kept on the premises at all times for inspection.

3.0 REGULATORY FRAMEWORK FOR ASBESTOS MANAGEMENT

Northern Trade Solutions are legally bound by the following Legislative requirements. Legislation requires a number of codes and regulatory documentation which apply to the identification and management of asbestos containing materials in buildings and plant.

Northern Trade Solutions have identified the most important of these legislative requirements as follows:

- Work Health and Safety (National Uniform Legislation) Act 2011 as in force 1st Jan 2012
- Work Health and Safety (National Uniform Legislation) Regulations as in force 19 Dec 2013
- Code of Practice: How to safely remove Asbestos
- Code of Practice: How to manage and control Asbestos in the workplace
- Code of Practice: How to manage Health and Safety risks

4.0 LIMITATIONS & DEFINITIONS

ASBESTOS refers to the fibrous form of mineral silicates arising from serpentine an amphibole rock forming minerals. These silicates in the Serpentine group include the following:

- Chrysotile (white Asbestos)
- Amphibole group
- Amosite (brown Asbestos)
- Crocidolite (blue Asbestos)
- Actinolite, tremolite and anthophyllite

Asbestos may also be considered as any mixture of the above definitions.

Asbestos is known to have been used over 3,000 building products and applications, the most common being fibro cement products, vinyl flooring, electrical switchboards and insulation materials to hot water and steam pipes, however, Asbestos can also be found in many other products located in inaccessible components of buildings, plant and equipment including the following areas:

- Interior parts of air conditioning systems
- Wall cavities, slabs, expansion joints and undersides of floors and coverings
- Interior workings of pumps and boilers
- Services, in ceiling or floor spaces or in-ground/underground service pits
- Wall chased lagged pipe work
- Floor coverings and underlay's
- Where Asbestos products have been removed (e.g. vinyl floor coverings), the glues and mastics that may contain Asbestos often remains due to the difficulty in the removal of such substances

Whilst this Survey and Register has been prepared in a manner consistent with the level of quality and skill generally exercised by members of Northern Trade Solutions strict professional quality control systems, this document must be read and interpreted subject to the following limitations:

- The Survey and Register has been prepared solely for the purpose described in the scope of works. This Survey and Register should not be relied on, or used by, the client for any other purpose other than the defined scope of works for which this document was prepared whatsoever.
- Where information referred to in the survey was obtained from third parties, and that Northern Trade Solutions has not independently verified the accuracy or comprehensiveness of the information supplied and accepts no responsibility or liability arising from any inaccuracies or omissions in the information supplied.
- Although care was taken during the site inspection to identify all asbestos containing materials at the site, Asbestos may be present at the site in concealed or inaccessible areas.
- The information contained in this Survey and Register are based on the conditions that existed at the date of the initial report and sampling date. No responsibility will be accepted for matters or events arising after that date. In particular, the Survey and Register cannot be relied on if alteration or demolition work is undertaken in the future or if site conditions change or are altered after the date of the acceptance of this document.

- This Survey and Register is not for the purposes of an Occupational Health and /Safety assessment, and must not in any part be duplicated in work place reviews, in the interpretation of the legal obligations pertaining to the site or as an assessment of compliance of the site with legal standards or obligations or subsequent regulations.
- The information contained in this document should only be presented in full and may not be used to support any other objectives other than those stated in this document pertaining to the scope of works. In particular, the Asbestos materials register, and other appendices attached to the document should not be separated from the body of the document for any other purpose or use whatsoever.
- This document should not be used for the purpose of tendering, preparing costing or budgets, programming of work, refurbishment of work or demolition works by any other persons other than Northern Trade Solutions representative's scope of relevance.

Whilst this report may provide approximate measurement and quantities of some materials found, we stress that they are approximate only. Accurate details would require a further visit to the site unless otherwise indicated in the scope of works for Northern Trade Solutions use and purposes.

The work involved in preparing an Asbestos Register is based on visual inspection of the building and/or plant and equipment, as well, representative samples of suspect materials are collected and reasonable assumption are made from those samples. These samples may not be a true representation of every element, part or component of the area of material concerned. Further, it is becoming increasingly apparent that some building materials containing Asbestos have been removed and replaced by non-Asbestos containing materials, particularly cement sheeting, in numerous cases only partial removal has occurred, leaving asbestos products remaining and this is often painted. While appropriate sampling has occurred the only sure determinant is to sample and analyse every section or piece in question. Full clarification would require a further visit to the site to obtain and analyse appropriate samples, unless otherwise indicated within the scope of work for Northern Trade Solutions.

This Survey and Register includes the Scope of Works for most and the client request, but further to this document includes known Asbestos building products detected in the course of the inspection. Additionally, where applicable, assumptions made on where Asbestos is likely to be found are also stated, in some cases, builders have been known to mix Asbestos into other materials that would not normally contain Asbestos (e.g. mortar, plaster, renders etc.) and, unless stated otherwise, these have not been sampled during the course of this Survey and have not been included into the register. If an inaccessible area is suspected of having Asbestos, it may need further verification, the decision regarding this will remain purely at the discretion of the client.

There is no known instrument available for in-situ Asbestos detection. Asbestos is a naturally occurring mineral of inert characteristics, for the above reasons, including the inaccessibility of many Asbestos products, no guarantee can be given, expressed or implied, and that the inspection will reveal all the Asbestos that may be located in the property described in this report.

5.0 RISK EVALUATIONS

Introduction

A qualitative risk evaluation was performed to identify the hazards posed to site occupants by the ACM's identified on the site. The evaluation consists of risk assessment on the identified ACM's and assigning a priority rating system for the management of such materials.

Methodology

Assessment of Risk

The risk evaluation is based on an assessment of a range of factors, such as the friability, location and condition of the identified materials.

In addition, the auditors have also considered the nature of the work in relation to the vicinity of the building occupants. In all circumstances the methods adopted have aimed to minimise the likelihood of fibres releasing into occupied space.

Priority Rating System

The priority rating systems in the following section were designed as a guide for the development of a management plan. The actual setting of priorities for implementation of control procedures will depend not only on the allocated rating, but also on factors such as changes to work practices or the physical environment that occur during refurbishment or demolition. In spite of this, the allocated rating does provide a reasonable guide to the appropriate priority setting with regard to the current condition of the materials.

Priority Ratings

Asbestos Containing Materials Ratings

There are four priority ratings in the system as outlined below. They are a guide only and the client should decide the most appropriate controls based on such factors as risk, detailed knowledge of workplaces and procedures, plans for upgrade or refurbishment.

Priority Rating for Control of Asbestos Containing Materials

Priority 1 – P1	Immediate Risk Level
<p>This level of risk is applicable to the presence of friable material, such as limpet asbestos insulation and asbestos ropes, especially if in a deteriorating state. It presents an immediate health risk in its current condition and location and immediate control measures are required, the area containing this material should be isolated, at the first instance, from personnel. Abatement is highly recommended at the earliest practicable time.</p>	

Priority 2 – P2	Potential Risk Level
<p>This level of risk is applicable to damaged or unstable material such as broken or deteriorated cement sheeting, which presents a potential health risk if disturbed, control measures to stabilise the material should be initiated immediately to prevent the chance of the contamination spreading to other areas, formal abatement should be considered</p>	

Priority 3 – P3	Low Risk Level
<p>This level of risk is applicable to damaged non-friable or stable material that may require some minor maintenance. Maintenance work should be carried out to stabilise and repair the damaged area. Control must be implemented to protect these materials from further damage or deterioration.</p>	

Priority 4 – P4	Negligible Risk Level
<p>This level of risk is applicable to non-friable or stable materials, such as painted cement sheeting, vinyl floor tiles, etc. It is unlikely for these materials to present a health risk unless damaged, cut, sanded, abraded or machined, these materials should be maintained in good condition and reassessment of the priority rating will be required if any maintenance or building works impact on their condition.</p>	

6.0 CONCLUSIONS & RECOMMENTATIONS

The inspection carried out **HAS NOT IDENTIFIED ASBESTOS** in ANY of the building materials at or in the Karama Shopping Plaza.

It is important to note that if Asbestos product are disturbed, asbestos fibres may be released, thereby resulting in a health risk. Great care therefore must be exercised in the immediate an ongoing management of any products found to contain Asbestos.

7.0 INSPECTION REPORT

An inspection of the areas was undertaken using a systematic procedure developed by Northern Trade Solutions. As previously stated, the identification of asbestos and/or products containing Asbestos cannot be carried out with any known in situ measuring instrument and final confirmation of Asbestos can only be done under microscopic examination. The inspection procedure developed relies on identifying Asbestos bearing materials by visual means. Representative samples of materials that are considered to contain Asbestos are often taken for analysis to confirm the presence of Asbestos.

Full details of all asbestos products located within the property are found within Appendix C of this document. Section 2 outlines suggested management procedures.



APPENDIX B

INSPECTION DETAILS


DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC001 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Kebab Karama	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC002 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Panda Takeaway	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC003 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Karama Dental	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	


DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC004   <p>Wednesday, 25 March 2015 14:37:13 37 Kalymnos Drive, Karama NT 0812, Australia</p>
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	NT Optometrist	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC005 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Lyndalls	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	



DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC006 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Brumbys	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	



DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC007 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Karama Post Office	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	






DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC008 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Delia Lawrie	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC009 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Dominos	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	


DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC010  <p>Wednesday, 25 March 2015 14:54:23 37 Kalymnos Drive, Karama NT 0812, Australia</p>
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Unwind	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	 <p>Wednesday, 25 March 2015 14:54:47 37 Kalymnos Drive, Karama NT 0812, Australia</p>




DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC011  <small>Wednesday, 25 March 2015 14:58:43 37 Kalymnos Drive, Karama NT 0812, Australia</small>
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	KSC011	
LOCATION DETAILS	Karama Medical Centre	
BUILDING MATERIAL BUILDING TYPE	Gyprock Cement Sheet above door SMP	
MATERIAL CONDITION	Good	
ASSESSOR	Tracy Allen NTWS-AA-439630	 <small>Wednesday, 25 March 2015 14:59:13 37 Kalymnos Drive, Karama NT 0812, Australia</small> <small>Wednesday, 25 March 2015 15:00:47 37 Kalymnos Drive, Karama NT 0812, Australia</small>

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC012 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Karama Child and Family Health	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC013,14,15,16,18,19,20
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	 <p>Wednesday, 25 March 2015 15:09:06 Karama Shopping Plaza, 69-73 Koolinda Crescent, Karama NT 0812, Australia</p>  <p>Wednesday, 25 March 2015 15:12:19 37 Kalymnos Drive, Karama NT 0812, Australia</p>  <p>Wednesday, 25 March 2015 15:12:42 52 Koolinda Crescent, Karama NT 0812, Australia</p>  <p>Wednesday, 25 March 2015 15:13:04 52 Koolinda Crescent, Karama NT 0812, Australia</p>  <p>Wednesday, 25 March 2015 15:15:38 37 Kalymnos Drive, Karama NT 0812, Australia</p>
SAMPLE I.D	NA	
LOCATION DETAILS	Fire Access Doors	
BUILDING MATERIAL BUILDING TYPE	Wood Interior unknown (the age of the building indicates that these doors are not ACM	
MATERIAL CONDITION	Good	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC021 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Karama Library	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC022 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	KSC022	
LOCATION DETAILS	Karama Shopping Plaza western entrance Soffit between Karama Library and Celebrations	
BUILDING MATERIAL BUILDING TYPE	Cement Sheet SMF	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	


DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC023  <p>Wednesday, 25 March 2015 15:26:37 37 Kalymnos Drive, Karama NT 0812, Australia</p>  <p>Wednesday, 25 March 2015 15:27:12 3 Karama Crescent, Karama NT 0812, Australia</p>  <p>Wednesday, 25 March 2015 15:30:44 37 Kalymnos Drive, Karama NT 0812, Australia</p>
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Celebrations Bottleshop	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC024 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Karama Plaza front entrance Facia surround	
BUILDING MATERIAL BUILDING TYPE	Cement Sheeting SMF	
MATERIAL CONDITION	Good	
ASSESSOR	Tracy Allen NTWS-AA-439630	


DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC026 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Karama Newsagency	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC027 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Value Plus Discount Pharmacy	
BUILDING MATERIAL BUILDING TYPE	Gyprock Non ACM vinyl tiles	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	



DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC029&30 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	KSC029,30	
LOCATION DETAILS	Female & Male cubicle divider rest rooms	
BUILDING MATERIAL BUILDING TYPE	Gyprock Cement Sheet non ACM	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	


DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC031 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	KSC031	
LOCATION DETAILS	Karama Tavern staff Male & Female ablutions	
BUILDING MATERIAL BUILDING TYPE	Gyprock Cement Sheet non ACM	
MATERIAL CONDITION	Good	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC032 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	NA	
LOCATION DETAILS	Karama Tavern	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC033 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D		
LOCATION DETAILS	Woolworths Staff	
BUILDING MATERIAL BUILDING TYPE	Gyprock	
MATERIAL CONDITION	Good	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC034 
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D		
LOCATION DETAILS	Woolworths Staff Toilets	
BUILDING MATERIAL BUILDING TYPE	laminated wood	
MATERIAL CONDITION	New	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC035  
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	KSC035	
LOCATION DETAILS	Woolworths loading dock area wall linings	
BUILDING MATERIAL BUILDING TYPE	Cement Sheeting non ACM	
MATERIAL CONDITION	Good	
ASSESSOR	Tracy Allen NTWS-AA-439630	

DATE OF ASSESSMENT	27.03.2015	Photo I.D. KSC036  <p>Wednesday, 25 March 2015 15:30:44 37 Kalymnos Drive, Karama NT 0812, Australia</p>
LOCATION	Karama Shopping Plaza Kalymnos Drive, Karama	
SAMPLE I.D	KSC036	
LOCATION DETAILS	Karama Tavern old Keg Lines	
BUILDING MATERIAL BUILDING TYPE	PVC	
MATERIAL CONDITION	Good	
ASSESSOR	Tracy Allen NTWS-AA-439630	

APPENDIX C

ASBESTOS REGISTER							
WORKPLACE ADDRESS; Karama Shopping Plaza				NAME OF COMPETENT PERSON; Tracy Allen Asbestos Assessor Asbestos licence number: NTWS-AA-439630			
Date of identification	I.D number	Type of Asbestos	Is it friable or non-friable	Condition of Asbestos	Specific location of asbestos	Is this an inaccessible area?	Priority rating

No Asbestos has been Identified at the Karama Shopping Plaza

APPENDIX D

LABORATORY RESULTS



OCTIEF PTY LTD
ABN: 82 163 772 478
 Base Site: Unit 34 53-57 Link Dr Yatala, QLD 4207
 Branch Site: Unit 12 16 Charlton Ct Woolner NT 0820
 Enquiries: 1800 628 433
 Fax: (07) 3382 6895
corporate@octief.com.au
www.octief.com.au

Asbestos Bulk Sample Analysis Report

Certificate No NT1503261403

Client:	Northern Trade Solutions	Sampled By:	Tracy
Client Contact:	Gerry Koukouvas	# of Samples Submitted:	8
Telephone:	0459 035 600	Sampling Date:	25/03/2015
Email:	gerry@ntsnt.com.au	Date Received:	26/03/2015
Project:	-	Identification Date:	26/03/2015
Site Location:	Karama Shopping Centre, Kalymnos Rd	Issue Date:	27/03/2015

Test Methodology: Polarized light microscopy examination including dispersion staining techniques for the presence of asbestos in accordance with the methodology outlined in the In-House Procedure QP-930-001 which is based on Australian Standard (AS4964-2004)

Branch Site: Darwin Laboratory

Sample ID	Sample Location	Sample Description	Size or Weight	Asbestos Detected (Yes/No)	Fibre Types Detected
KSC011	Karama surgery - Above door panel	Fibre cement sheeting	5x3x1mm	No	NAD-ORG
KSC022	West entrance - Soffit	Fibre cement sheeting	20x14x3mm	No	NAD-ORG
KSC024	Front entrance - Surround fascia	Fibre cement sheeting	18x12x3mm	No	NAD-ORG
KSC029	Ladies toilet - Cubicle dividers	Fibre cement sheeting	25x18x3mm	No	NAD-ORG
KSC030	Karama public toilet - Cubicle male	Fibre cement sheeting	28x20x3mm	No	NAD-ORG
KSC031	Karama tavern - Mens staff toilet	Fibre cement sheeting	15x10x3mm	No	NAD-ORG

Fibre Types

CHR	Chrysotile (white asbestos) fibres detected	ORG	Organic fibres detected
AMO	Amosite (brown / grey asbestos) fibres detected	SMF	Synthetic mineral fibres detected
CRO	Crocidolite (blue asbestos) fibres detected	UMF	Unidentified mineral fibres detected
NFD	No fibres detected	NAD	No Asbestos Detected

Notes

Hand-picked refers to small discrete amounts of asbestos distributed unevenly in a large body of non-asbestos material.

Detection limit (AS 4964) – 0.1 g/kg.

Due to their nature, confirmation using another independent analytical technique is recommended if no asbestos is detected in samples of vinyl tiles, bituminous materials, mastics, adhesives, paints, sealants, resins or ore.

The results contained within this report relate only to the sample(s) submitted for analysis and OCTIEF accepts no responsibility for the collection, packaging and transportation of sample submitted by external parties. Sample descriptions, sizes and weights are approximate only. NATA does not accredit sampling.



This document is issued in accordance with NATA's accreditation requirements
 Accredited for compliance with ISO/IEC 17025
 NATA accreditation number: 15172
 This document may not be reproduced except in full

Page 1 of 2



OCTIEF PTY LTD

ABN: 82 163 772 478

Base Site: Unit 34 53-57 Link Dr Yatala, QLD 4207

Branch Site: Unit 12 16 Charlton Ct Woolner NT 0820

Enquiries: 1800 628 433

Fax: (07) 3382 6895

corporate@octief.com.au

www.octief.com.au

Asbestos Bulk Sample Analysis Report

Certificate No NT1503261403

Sample ID	Sample Location	Sample Description	Size or Weight	Asbestos Detected (Yes/No)	Fibre Types Detected
KSC034	Woolworths - Wall lining stores	Fibre cement sheeting	28x25x3mm	No	NAD-ORG
KSC036	Karama tavern - Pipe casing	Cementitious material	20x18x6mm	No	NAD-NFD

Approved Identifier:



Dean Anderson

Report Approved By:



John Quinones

Fibre Types

CHR Chrysotile (white asbestos) fibres detected

AMO Amosite (brown / grey asbestos) fibres detected

CRO Crocidolite (blue asbestos) fibres detected

NFD No fibres detected

ORG

SMF

UMF

NAD

Organic fibres detected

Synthetic mineral fibres detected

Unidentified mineral fibres detected

No Asbestos Detected

Notes

Hand-picked refers to small discrete amounts of asbestos distributed unevenly in a large body of non-asbestos material.

Detection limit (AS 4964) – 0.1 g/kg.

Due to their nature, confirmation using another independent analytical technique is recommended if no asbestos is detected in

APPENDIX E

AUDIT SUMMARY

INTRODUCTION

Northern Trade Solutions have received a purchase order to conduct a extensive survey and Asbestos register to the all areas at the, Karama Shopping Plaza, from Peter LaPira.

SITE DESCRIPTION

The site is of a large shopping complex built in 1992 and Extensively Renovated in the past 3years located on Kalymnos Drive Karama

AREAS INCLUDED

All areas in the public domain and tenancies.

AREA EXCLUDED

All internal plant, under building voids and the Woolworths ceiling tiles due to the need of high platform access. (this area is highly suspected to be Gyprock).

COMMENTS

There were no difficulties in accessing all areas that have not already been listed.

SURVEY FINDINGS

This building is constructed mainly in Gyprock Ceiling tiles, ceramic tile flooring, block and steel due to the nature of such a building and its many stake holders the interiors of the building consist of many types of building materials. As this survey and register is requested for the entire area internally and externally, some cladding materials that are typical of Asbestos containing materials have been identified and resolved as containing Synthetic Mineral Fibres. Northern Trade Solutions has had the samples assessed by a NATA laboratory and they have determined that the samples taken from the Karama Shopping Plaza contain no Asbestos Containing Materials.

NOTES: