

## Asbestos Containing Materials Survey - Part 5



Property Number (PMS): GRC009  
Property Name: GRC Properties  
Property Address: 133 Mitchell Street Larrakeyah NT  
0820

Number of Structures: 1  
Report Creation Date: 22 Oct 2021

Asbestos Solutions NT  
PO Box 42110  
Casuarina NT 0811  
Tel: 0451 832 064  
Email: [asbestossolutionsnt@bigpond.com](mailto:asbestossolutionsnt@bigpond.com)

# Audit Summary

## Introduction

Asbestos Solutions NT Pty Ltd were contracted by GRC Properties to conduct a Part 5 Asbestos Audit on the Building located at 133 Mitchell Street Larrakeyah NT 0820

## Site Description

The site is a Single story Office building.

## Area Included

All structures on the site.

## Area Excluded

All underground Power, Water and Sewerage services.

## Comments

All Asbestos materials are in Stable painted condition.

## Survey Findings

Refer to Appendix A in the Register.

# Contents

<b>1</b>	<b>Definitions</b> .....	<b>1</b>
<b>2</b>	<b>Introduction</b> .....	<b>2</b>
	2.1 Background.....	2
<b>3</b>	<b>Scope of Works</b> .....	<b>3</b>
	3.1 Purpose.....	3
	3.2 Nature of Survey.....	3
<b>4</b>	<b>Limitations</b> .....	<b>3</b>
	4.1 Conditions of Engagement .....	3
	4.2 Accuracy .....	4
	4.3 Completeness of Inspection.....	4
<b>5</b>	<b>Methodology</b> .....	<b>5</b>
	5.1 Firedoors .....	6
	5.2 Vinyl Tiles.....	6
	5.3 Air Conditioning Ducts .....	6
	5.4 Sampling Procedures.....	6
<b>6</b>	<b>Risk Evaluation</b> .....	<b>7</b>
	6.1 Introduction.....	7
	6.2 Methodology.....	7
	6.3 Priority Ratings.....	8
<b>7</b>	<b>References</b> .....	<b>10</b>

**Appendix A: Asbestos Register**

**Appendix B: Laboratory Results**

**Appendix C: Site Plan**

## Definitions

---

### **Act**

An Act is a primary legislative instrument - it may give authority for the making of another legislative instrument. The role of an Act is to constitute the process of formulating general rules or conduct without reference to particular cases and they usually operate in the future. Acts state the general principles of a scheme.

### **Asbestos**

Asbestos refers to the fibrous form of mineral silicates arising from serpentine and amphibole rock forming minerals. These silicates include:

#### Serpentine Group

- Chrysotile (white asbestos)
- Amphibole Group
- Amosite (brown asbestos)
- Crocidolite (blue asbestos)
- Actinolite, tremolite and anthophyllite.

Asbestos may also be considered as any mixture of the above groups.

Materials containing asbestos may include “fibro” products, spray-on fireproofing, soundproofing/thermal insulation, acoustic plaster, and insulation and friction materials such as brake linings, clutch pads, gaskets and seals.

Asbestos has been used as insulation for pipes, autoclaves, ovens, mattresses, heat blankets, rope, vinyl tiles, fire doors, building material (sheet), piping, laboratory bench tops, switchboards, clutch linings, batteries and many other uses.

Asbestos is typically found in buildings more than 25 years old, as cement sheeting, spray-on fireproofing, black electrical mounting boards, vinyl flooring, asbestos wire insulation and at times, within boilers and heating units.

### **Asbestos Cement Sheet (AC)**

Asbestos cement sheet is a building material, which is a composite of asbestos fibres, plant fibres, cement and sand. This includes flat or corrugated compressed sheeting, pipes and roof shingles.

### **Asbestos Containing Materials (ACM's)**

Asbestos containing materials are any material that contain asbestos.

### **Asbestos Related Activities**

Activities which involve the identification, evaluation and control of asbestos situations, including removal.

## Code of Practice

A Code of Practice provides practical guidance for prevention, assessment and control of the subject matter. It is designed to assist in the implementation of the provisions of associated regulations.

## Friable

The term friable is used to describe asbestos containing material or synthetic mineral fibres that can be crumbled, pulverised or reduced to particles by hand pressure when dry. Friable asbestos is considered to represent a particular hazardous state. It typically includes spray-on insulation, fireproofing or soundproofing.

## Presumption Criteria

Where samples have not been taken (i.e. restricted access) the suspect samples are simply presumed to contain asbestos. Or if materials historically contain asbestos and visual inspection confirms the likelihood that asbestos is present (i.e. gaskets) then again these areas are presumed to contain ACM. The presumption criteria can also be used where a facility contains multiple suspected areas which likely contain ACM (i.e. fire doors).

Once the presumption has been made the material must be treated as an ACM with work practices and disposal criteria as required for the presence of asbestos, until the material is removed or testing has confirmed that it does not contain asbestos.

## Regulation

Regulations deal with matters of administrative or technical detail, particularly where this detail may need to be changed from time to time.

# Introduction

---

## Background

Asbestos Solutions NT has been engaged to:

- Undertake a Part 5 re-survey of asbestos containing materials (ACM's) located at the site.
- Prepare an asbestos register.

This survey is to assist the client and building management in identifying the location of ACM's at the site and to provide a basis for the ongoing management.

## Scope of Works

---

### Purpose

The purpose of the asbestos survey is to identify the locations and condition of ACM's within the building and to provide advice in relation to appropriate ongoing management of the identified materials. This survey forms part of the overall responsibility as owner/occupier of the property.

### Nature of Survey

The surveys consisted of the following:

- An inspection of the property.
- Collection of samples (where required).
- Confirmation of existing ACM's and their condition
- The addition of any new suspected ACM's.
- Register update.

The survey was developed in accordance with the following codes of practice and guidelines:

- Code of Practice for the Management and Control of Asbestos in Workplaces. [NOHSC:2018 (2005)].

The asbestos survey did not include the following:

- An investigation or assessment of areas of the site that were not readily accessible or practicable to access on the day (including within switchboards, lift infrastructure, internal air conditioning and heating units). Practicable in this sense means that plant and equipment would have had to be dismantled, or unacceptable damage would have been incurred if the inspection had proceeded or in operation and therefore unsafe to investigate.
- Reviews of any licenses or approvals held in relation to the use, handling or presence of ACM's at the site, or past, current or proposed removal or treatment of ACM's at or from the site.

## Limitations

---

### Conditions of Engagement

Whilst this survey has been prepared in a manner consistent with the level of quality and skill generally exercised by members of Asbestos Solutions NT profession, it must be read and interpreted subject to the following limitations:

- The survey was prepared solely for the purpose described in Section 2.1. It should not be relied on, or used by, the client for any other purpose.

- The survey was prepared solely for the client and should not be relied on, or used by, any other party for any purpose whatsoever.
- Where information referred to in the survey was obtained from third parties, Asbestos Solutions NT has not independently verified the accuracy or comprehensiveness of the information supplied and accepts no responsibility or liability arising from any inaccuracies or omissions in the information supplied.
- Although care was taken during the site inspection to identify all asbestos containing materials at the site, asbestos may be present at the site in concealed areas or locations of the property not accessed at the time of inspection.
- The information contained in this survey is based on conditions that existed at the date of the survey. No responsibility for matters or events arising after that date is accepted. In particular, the survey cannot be relied on if alteration or demolition work is undertaken in the future or if site conditions change or are altered, after the date of the survey.
- The survey is not for the purposes of an Occupational Health and Safety (OH&S) Assessment. The survey is in no way to be considered or interpreted as a review of the legal obligations pertaining to the site or as an assessment of compliance of the site with legal standards or obligations or subsequent regulations.
- The information contained in this survey should only be presented in full and may not be used to support any other objectives other than those stated in this survey. In particular, the asbestos materials register, and other appendices attached to the survey should not be separated from the body of the survey for any purpose or use whatsoever.
- This survey should not be used for the purpose of tendering, preparing costing or budgets, programming of work, refurbishment of works or demolition work.

## Accuracy

The information contained in this survey is considered to be accurate on the date of the survey in accordance with the current conditions of the site. These conditions may vary from time to time as the result of further activity that may influence the condition of the ACM's identified at the site. In addition, limited non destructive sampling was undertaken at the site. As a result the inspection cannot be regarded as absolute.

## Completeness of Inspection

Locations where the assessment of asbestos may not have been practicable include, but are not limited to:

- Internal sections of air-conditioning systems and hot water/heating systems, wall partitions, fire doors and electrical light fittings.

- Concealed or inaccessible areas or voids within the building such as wall cavities, beneath floors, carpets and slabs, above fixed ceilings and confined spaces.
- Integral parts of boilers, pumps, machinery, plant and pipe work.
- Areas where the presence of asbestos containing materials was not considered to represent a significant exposure risk.
- ACM's concealed by other materials, preventing visual access or identification or installed in non-typical applications.

No asbestos survey can guarantee to identify all ACM's present in a building. Whilst this survey has been prepared in a manner consistent with the level of quality and skill generally exercised by members of Asbestos Solutions NT profession, there is no guarantee, expressed or implied, that all ACM's have been identified in this survey.

Based on the above information, further investigation and sampling will be required prior to demolition or refurbishment works.

## Methodology

---

The inspection consisted of a visual check of suspected asbestos materials within the premises and sampling when required based on professional judgement.

Details of the sample collection are provided below and the results are provided in Appendix A.

The methodology is a risk-based approach, which seeks to identify ACM that are commonly found at properties more than 25 years old. The approach involves both visual and laboratory identification of ACM's which are readily accessible at the property, and may represent a health risk if disturbed.

Where samples are not able to be taken it is sometimes necessary to presume the material contains asbestos. Once such a presumption has been made, the material must be treated as an asbestos containing material until it is confirmed by analysis or removed.

Samples were not taken from the following materials suspected as containing asbestos:

- Switchboards located throughout the building.
- Fire Doors.
- Air Conditioning ducts.
- Vinyl tiles.
- Mastics, sealants, adhesives and paints.



These have not been sampled because in some cases these materials are considered low risk, samples are not possible (i.e. from fire doors as sampling effects the integrity of the door) or for economic reasons.

## Firedoors

While all care has been exercised to ensure all fire doors have been checked and labelled it is possible that some fire doors have been missed or were not accessible during the audit. Asbestos free fire doors will be labelled "Asbestos Free" on the nameplate or will have a recently dated nameplate. Before any work is performed on any fire door Asbestos Solutions NT that the nameplate is checked in consultation with the register, if there is any doubt then the fire door should be treated as containing asbestos until verified otherwise.

## Vinyl Tiles

While all care has been exercised to ensure all vinyl tiles have been checked and labelled it is possible that some vinyl tiles have been missed, were not accessible during the audit or previous analysis have concluded that the tile does not contain asbestos (when in fact due to the non-homogeneous nature of vinyl tiles it may contain asbestos, just not in the area sampled). If there is any doubt about whether a vinyl tile contains asbestos then the vinyl tile should be treated as containing asbestos until verified otherwise.

## Air Conditioning Ducts

While all care has been exercised to ensure all HVAC systems have been checked for ACM millboard it is possible that some ACM components have been missed or were not accessible during the audit. If there is any doubt about whether a HVAC system contains ACM's then the system should be treated as containing asbestos until verified otherwise.

## Sampling Procedures

### **Asbestos Containing Materials**

All samples were collected using pinch pliers or other appropriate sampling equipment. While samples were being collected, all relevant safety procedures were adhered to in accordance with relevant OH&S procedures and Codes of Practice. Suspected materials are regarded as potentially containing asbestos and full precautions applied.

Samples were collected from suspected ACM's and particularly those of a friable nature. A discrete and non-destructive technique of sampling was used to minimise any obvious sign of damage and limit any damages to the integrity of the material.

Due to the operating nature of the premises, no samples were taken from within air plenums such as air conditioning fan rooms, operating furnaces, fire doors, heaters or other locations where non-destructive safe sampling cannot be conducted.

All tools were cleaned throughout, following each sample collection, to prevent any cross contamination, in some cases, adjoining areas were also wiped clean. All disposable materials, which were likely to have come in contact with any ACM's, were double sealed into plastic bags for subsequent disposal.

In all cases attention was paid to the collection of representative samples. When variations in colour, texture, etc. were noted, additional sampling was initiated.

Asbestos containing materials not considered to represent a significant exposure risk include, but are not limited to; paints, mastics, sealants, adhesives and similar materials. Such materials were typically not sampled.

### **Field Log-Sheets**

The field inspector recorded each sample of suspected ACM's on a field log-sheet as it was collected. Such field log-sheets include information on the date, time, sampling location and sample number.

### **Sample Labelling**

Each sample of suspected asbestos was placed in an individual re-sealable plastic bag, which was sealed in a second plastic bag before dispatch to the laboratory. Each bag was then labelled with a unique numbering system, which enabled laboratory staff to identify and track samples.

### **Sample Examination**

Samples were analysed by NATA certified laboratories that use polarised light microscopy and X-ray diffraction to identify the presence of asbestos.

## **Risk Evaluation**

---

### **Introduction**

A qualitative risk evaluation was performed to identify the hazards posed to site occupants by the ACM's identified on the site. The evaluation consists of risk assessment on the identified ACM's and assigning a priority rating system for the management of such materials.

### **Methodology**

#### **Assessment of Risk**

The risk evaluation is based on an assessment of a range of factors, such as the friability, location and condition of the identified materials.

In addition, the auditors have also considered the nature of the work in relation to the vicinity of the building occupants. In all circumstances the methods adopted have aimed to minimise the likelihood of fibres releasing into occupied space.

The above factors have been utilised in the process of determining appropriate recommendations for the timing of assessment activities and have assisted in the development of the management plan.

### **Priority Rating System**

The priority rating systems in the following section were designed as a guide for the development of a management plan. The actual setting of priorities for implementation of control procedures will depend not only on the allocated rating, but also on factors such as changes to work practices or the physical environment that occur during refurbishment or demolition. In spite of this, the allocated rating does provide a reasonable guide to the appropriate priority setting with regard to the current condition of the materials.

## **Priority Ratings**

### **Asbestos Containing Materials Ratings**

There are four priority ratings in the system as outlined below. They are a guide only and the client should decide the most appropriate controls based on such factors as risk, detailed knowledge of workplaces and procedures, plans for upgrade or refurbishment.

## Priority Rating for Control of Asbestos Containing Materials

<b>Priority 1 – P1</b>	<b>Immediate Risk Level</b>
<p>This level of risk is applicable to the presence of friable material, such as limpet asbestos insulation and asbestos ropes, especially if in a deteriorating state. It presents an immediate health risk in its current condition and location and immediate control measures are required. The area containing this material should be isolated, at the first instance, from personnel. Abatement is highly recommended at the earliest practicable time.</p>	

<b>Priority 2 – P2</b>	<b>Potential Risk Level</b>
<p>This level of risk is applicable to damaged or unstable material such as broken or deteriorated cement sheeting, which presents a potential health risk if disturbed. Control measures to stabilise the material should be initiated immediately to prevent the chance of the contamination spreading to other areas. Formal abatement should be considered.</p>	

<b>Priority 3 – P3</b>	<b>Low Risk Level</b>
<p>This level of risk is applicable to damage non-friable or stable material that may require some minor maintenance. Maintenance work should be carried out to stabilise and repair the damaged area. Control must be implemented to protect these materials from further damage</p>	

<b>Priority 4 – P4</b>	<b>Negligible Risk Level</b>
<p>This level of risk is applicable to non-friable or stable materials, such as painted cement sheeting, vinyl floor tiles, etc. It is unlikely for these materials to present a health risk unless damaged, cut, sanded, abraded or machined. These materials should be maintained in good condition and reassessment of the priority rating will be required if any maintenance or building works impact on their condition.</p>	

## References

---

- How to Safely Remove Asbestos: Code of Practice. Safe Work Australia. December 2011.
- How to Manage and Control Asbestos in the Workplace: Code of Practice. Safe Work Australia. December 2011.
- Guidance Note on the Membrane Filter Method for Estimating Airborne Asbestos Fibres. 2nd Edition. WorkSafe Australia, [NOHSC: 3003 (2005)]

# Appendix A

---

Asbestos Register

## Building ID: B01

LOCATION	DETAILS	RISK	Asbestos
Deposit ID: GRC001 Sample ID: 680 10041.00000/ 13 Ground Eaves and Facia 	<b>Application:</b> Linings <b>Description:</b> Cement Sheet <b>Accessibility:</b> Accessible <b>Amount:</b> 100 m <sup>2</sup> <b>Recommendations:</b> Removal by Licenced Asbestos removalist only. <b>Due Date:</b>	<b>Status:</b> Present <b>Substance Type:</b> Chrysotile <b>Condition:</b> Good <b>Damage or Deterioration Potential:</b> Low <b>Activities that May Disturb Material:</b> Tradesman/personnel <b>Remedial Action:</b> Maintain <b>Audit Findings:</b> Eaves contain Asbestos as previously tested by SLR Consultants 24th July 2013. Warning labels present. <b>Assessed:</b> 2021-10-07 <b>Risk Ass.</b> P4	
Deposit ID: GRC004 Sample ID: Ground Roof 	<b>Application:</b> Linings <b>Description:</b> Tiles - Metal sheeting <b>Accessibility:</b> Not Accessible <b>Amount:</b> 400 <b>Recommendations:</b> If Roof is to be replaced insure testing is done prior to confirm if the tiles contain Asbestos. <b>Due Date:</b>	<b>Status:</b> Assumed Present <b>Substance Type:</b> <b>Condition:</b> Moderate <b>Damage or Deterioration Potential:</b> Low <b>Activities that May Disturb Material:</b> Tradesman/personnel/weather <b>Remedial Action:</b> Leave Alone <b>Audit Findings:</b> Metal Roof Sheetting possibly contains Asbestos - Decromastic tile. No sample due to access. <b>Assessed:</b> 2021-10-21 <b>Risk Ass.</b> P4	
Deposit ID: GRC003 Sample ID: 680 10041.00000/ 13 Ground Garage Garage Ceiling 	<b>Application:</b> Linings <b>Description:</b> Cement Sheet <b>Accessibility:</b> Accessible <b>Amount:</b> 25 m <sup>2</sup> <b>Recommendations:</b> <b>Due Date:</b>	<b>Status:</b> Present <b>Substance Type:</b> Chrysotile <b>Condition:</b> Good <b>Damage or Deterioration Potential:</b> Low <b>Activities that May Disturb Material:</b> Tradesman/personnel <b>Remedial Action:</b> Maintain <b>Audit Findings:</b> Ceiling contains Asbestos as previously tested by SLR Consultants 24th July 2013. <b>Assessed:</b> 2021-10-08 <b>Risk Ass.</b> P4	
Deposit ID: GRC002 Sample ID: 680 10041.00000/ 13 Ground Garage Walls 	<b>Application:</b> Linings <b>Description:</b> Cement Sheet <b>Accessibility:</b> Accessible <b>Amount:</b> <b>Recommendations:</b> <b>Due Date:</b>	<b>Status:</b> Present <b>Substance Type:</b> Chrysotile <b>Condition:</b> Good <b>Damage or Deterioration Potential:</b> Low <b>Activities that May Disturb Material:</b> Tradesman/personnel <b>Remedial Action:</b> Maintain <b>Audit Findings:</b> Eaves contain Asbestos as previously tested by SLR Consultants 24th July 2013. <b>Assessed:</b> 2021-10-01 <b>Risk Ass.</b> P4	

## Building ID: B01

LOCATION	DETAILS	RISK	Asbestos
Deposit ID: GRC007 Sample ID: Ground Power Meter Box Meter Box 	<b>Application:</b> Mounting board <b>Description:</b> Insulation panel <b>Accessibility:</b> <b>Amount:</b> <b>Recommendations:</b> <b>Due Date:</b>	<b>Status:</b> Present <b>Substance Type:</b> Chrysotile <b>Condition:</b> Moderate <b>Damage or Deterioration Potential:</b> Low <b>Activities that May Disturb Material:</b> Tradesman/personnel <b>Remedial Action:</b> Leave Alone <b>Audit Findings:</b> Meter panels contain Asbestos material. <b>Assessed:</b> 2021-10-21 <b>Risk Ass.</b> P4	
Deposit ID: GRC006 Sample ID: Ground Throughout Ceilings 	<b>Application:</b> Linings <b>Description:</b> Plasterboard <b>Accessibility:</b> <b>Amount:</b> <b>Recommendations:</b> <b>Due Date:</b>	<b>Status:</b> Not Present <b>Substance Type:</b> <b>Condition:</b> <b>Damage or Deterioration Potential:</b> <b>Activities that May Disturb Material:</b> <b>Remedial Action:</b> <b>Audit Findings:</b> <b>Assessed:</b> 2021-10-21 <b>Risk Ass.</b> None	
Deposit ID: GRC005 Sample ID: Ground Throughout Walls 	<b>Application:</b> Linings <b>Description:</b> Plasterboard/Masonry <b>Accessibility:</b> Accessible <b>Amount:</b> <b>Recommendations:</b> <b>Due Date:</b>	<b>Status:</b> Not Present <b>Substance Type:</b> <b>Condition:</b> <b>Damage or Deterioration Potential:</b> <b>Activities that May Disturb Material:</b> <b>Remedial Action:</b> <b>Audit Findings:</b> <b>Assessed:</b> 2021-10-21 <b>Risk Ass.</b> None	