Asbestos Register

19-23 Albatross St, WINNELLIE

| Level | Location | Material Description | Туре | Classification | Condition | Risk | Comments & Recommendations | Date Identified |
|----------|--|--|--|----------------|------------|----------|---|--------------------|
| Exterior | Plant Room Between Tenancies 1 & 2 (Buildings # 7 & 8) -Exterior- | 680.10025.00000/2 | Amosite Asbestos FCS – Fibre Cement Sheeting | Non Friable | Nil Damage | Low | Material Requires Labelling (20m2) Labelling Completed 30 Aug 2013. | 31 July 2013 |
| Exterior | Plant Room Between Tenancies 2 & 3 (Buildings #8 & 9) -Exterior- | Visually similar to item ref: 680.10025.00000/02 | Amosite Asbestos FCS – Fibre Cement Sheeting | Non Friable | Nil Damage | Low | Material Requires Labelling (20m2) Labelling Completed 30 Aug 2013. | 31 July 2013 |
| Exterior | Plant Room Between Tenancies 3 & 4 (Buildings # 9 & 10) -Exterior- | Visually similar to item ref: 680.10025.00000/02 | Amosite Asbestos FCS – Fibre Cement Sheeting | Non Friable | Nil Damage | Low | Material Requires Labelling (20m2) Labelling Completed 30 Aug 2013. | 31 July 2013 |
| Exterior | Switch room Between Tenancies 2 & 3 (Buildings # 8 & 9) | 680.10025.00000/3 | Asbestos EBB Electrical Backing Board | Non Friable | Nil Damage | Very Low | Material Requires Labelling (10m2) Labelling Completed 30 Aug 2013. Removed as part of Power & Water upgrade to substation works (C&R Construction) | 31 April 2015 |
| Exterior | Soffit ling to southern (Front) elevation of property. Vinyl floor tiles and adhesive backing to electrical cupboard | Assumed to contain Asbestos | Chrysotile and Amosite Asbestos *Assumed* | Non Friable | Nil Damage | Very Low | Material Requires Labelling (100m2) Labelling Completed 30 Aug 2013. | 31 July 2013 |
| NOTE | Building # 11 | N/A | N/A | N/A | N/A | N/A | Within the scope and limitations of the survey, no asbestos was identified or assumed onsite during the investigation | 31 July 2013 |

As per the report prepared 31st July 2013 – SLR Consulting Australia Asbestos Survey (Report # 680.10025.00050 ASR RO);

Within the scope and limitations of the survey, asbestos was identified or assumed onsite during the investigation.

Review Dates

| 31 July 2013 | Liam Munro / | SLR / Facilities manager | Initial Review | | |
|-----------------|--------------|--------------------------|--|--|--|
| | T.Waldron | | Items labelled as per report and will monitor over 12 months | | |
| 2014 - June | T.Waldron | Facilities Manager | General review of register | | |
| 2015 - February | T.Waldron | Facilities Manager | General review of register | | |
| 2016 - January | T.Waldron | Facilities Manager | General review of register | | |
| 2016 - July | T.Waldron | Facilities Manager | Proposed NEW tenant for Buildings 7 & 8 with minor fitout works to include | | |
| | | | new offices and mechanical services. | | |
| 2017 - December | T.Waldron | Facilities Manager | Minor Fitout to Building # 7 & 8 (NTPHN) | | |
| 2018 – January | T.Waldron | Facilities Manager | Demolition of External Wash bay (Building # 10) | | |
| 2018 - February | T.Waldron | Facilities Manager | Minor Fitout to Building # 10 (Heartcraft) | | |
| 2020 - January | T.Waldron | Snr Facilities Manager | General review of register. | | |
| 2021 - July | T.Waldron | Snr. Facilities Manager | Building # 9 - Badminton Fit out Review and Drawing set up | | |