

**ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)**  
**REGION - TIWI ISLAND SHIRE**  
**AUDIT REPORTS - 3457/2, 3457/3**  
**SURVEY DATES - 2008, 2009**  
**REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012**

ASSET IDENTIFICATION		ACM LOCATION & DESCRIPTION				SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
<b>Catholic Diocese of Darwin</b> Andy McCracken Property Manager GPO Box 476 DARWIN NT 0801 P: (08) 8942 6000 E: property@darwin.catholic.org.au M: 0447 349 889	107	Church Building	Y	Internal	Floor covering to altar	25	Brown vinyl tiles containing white (Chrysotile) asbestos	Some damage	12 - 36 months
<b>Catholic Diocese of Darwin</b> Andy McCracken Property Manager GPO Box 476 DARWIN NT 0801 P: (08) 8942 6000 E: property@darwin.catholic.org.au M: 0447 349 889	107	Church Building	Y	External	Wall cladding	50	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months
<b>Catholic Diocese of Darwin</b> Andy McCracken Property Manager GPO Box 476 DARWIN NT 0801 P: (08) 8942 6000 E: property@darwin.catholic.org.au M: 0447 349 889	107	Church Building	Y	External	Gable infill to east side	5	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months

**ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)**  
**REGION - TIWI ISLAND SHIRE**  
**AUDIT REPORTS - 3457/2, 3457/3**  
**SURVEY DATES - 2008, 2009**  
**REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012**

ASSET IDENTIFICATION		ACM LOCATION & DESCRIPTION				SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
<b>Catholic Diocese of Darwin</b> Andy McCracken Property Manager GPO Box 476 DARWIN NT 0801 P: (08) 8942 6000 E: property@darwin.catholic.org.au M: 0447 349 889	107	Church Building	Y	External	Infill to north and south central upper	4	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months
<b>Remote Community Housing</b>	174	Dwelling	Y	Internal	Ceiling lining in bathroom (5m2)	5	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months
<b>Remote Community Housing</b>	174	Dwelling	Y	Internal	Ceiling lining in toilet (2m2)	2	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months
<b>Remote Community Housing</b>	174	Dwelling	Y	Internal	Ceiling lining throughout (120m2)	120	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months
<b>Remote Community Housing</b>	175	Dwelling	Y	External	Ceiling lining to verandah (20m2)	20	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months
<b>Remote Community Housing</b>	175	Dwelling	Y	Internal	Ceiling lining in bathroom (5m2)	5	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months

**ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)**  
**REGION - TIWI ISLAND SHIRE**  
**AUDIT REPORTS - 3457/2, 3457/3**  
**SURVEY DATES - 2008, 2009**  
**REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012**

ASSET IDENTIFICATION		ACM LOCATION & DESCRIPTION				SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
Remote Community Housing	175	Dwelling	Y	Internal	Ceiling lining in toilet (2m2)	2	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months
Remote Community Housing	175	Dwelling	Y	Internal	Ceiling lining throughout (120m2)	120	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months
Responsible Entity Unknown	176	Vacant land	Y	Grounds	Cement pipe	<1	cement pipe	Poor	Less than 12 months
Responsible Entity Unknown	176	Vacant land	Y	Grounds	Debris - rubble pile at centre of lot	<1	Vinyl sheet material	Poor	Less than 12 months
<b>Tiwi Island Shire Council</b> Alan Hudson - CEO Po Box 104 Darwin NT 0804 P: (08) 8970 9501 E: alan.hudson@tiwiislands.nt.gov.au	178	Dwelling	Y	External	Electrical backing board	1	Area accessed but not sampled. Based on findings in similar areas, it is highly likely the resin backing board contains asbestos	Stable	Greater than 36 months
<b>Tiwi Island Shire Council</b> Alan Hudson - CEO Po Box 104 Darwin NT 0804 P: (08) 8970 9501 E: alan.hudson@tiwiislands.nt.gov.au	178	Dwelling	Y	External	Ceiling lining to eaves and carport (30m2)	30	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months

ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)  
 REGION - TIWI ISLAND SHIRE  
 AUDIT REPORTS - 3457/2, 3457/3  
 SURVEY DATES - 2008, 2009  
 REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012

ASSET IDENTIFICATION	ACM LOCATION & DESCRIPTION					SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
<b>Tiwi Island Shire Council</b> Alan Hudson - CEO Po Box 104 Darwin NT 0804 P: (08) 8970 9501 E: alan.hudson@tiwiislands.nt.gov.au	178	Dwelling	Y	Internal	Ceiling lining throughout	90	Cement sheet	Stable	Greater than 36 months
<b>Remote Community Housing</b>	195	Dwelling	Y	External	Bench top (1m2)	1	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months
<b>Remote Community Housing</b>	196	Dwelling	Y	External	Bench top (1m2)	1	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months
<b>Remote Community Housing</b>	233	Dwelling	Y	External	Electrical backing board	1	Area accessed but not sampled. Based on findings in similar areas, it is highly likely the resin backing board contains asbestos	Stable	Greater than 36 months
<b>Remote Community Housing</b>	233	Dwelling	Y	External	Ceiling lining to porch at rear (5m2)	5	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months

**ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)**  
**REGION - TIWI ISLAND SHIRE**  
**AUDIT REPORTS - 3457/2, 3457/3**  
**SURVEY DATES - 2008, 2009**  
**REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012**

ASSET IDENTIFICATION		ACM LOCATION & DESCRIPTION				SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
Remote Community Housing	234	Dwelling	Y	External	Electrical backing board	1	Area accessed but not sampled. Based on findings in similar areas, it is highly likely the resin backing board contains asbestos	Stable	Greater than 36 months
Remote Community Housing	234	Dwelling	Y	External	Infill to roof level front and rear (5m2)	5	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) and blue (Crocidolite) asbestos	Stable	Greater than 36 months
Remote Community Housing	235	Dwelling	Y	External	Electrical backing board	1	Area accessed but not sampled. Based on findings in similar areas, it is highly likely the resin backing board contains asbestos	Stable	Greater than 36 months
Remote Community Housing	236	Dwelling	Y	External	Infill to roof level front and rear (5m2)	5	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) and blue (Crocidolite) asbestos	Stable	Greater than 36 months

**ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)**  
**REGION - TIWI ISLAND SHIRE**  
**AUDIT REPORTS - 3457/2, 3457/3**  
**SURVEY DATES - 2008, 2009**  
**REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012**

ASSET IDENTIFICATION	ACM LOCATION & DESCRIPTION					SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
Government Employee Housing	237	Dwelling	Y	External	Infill around laundry external (5m2)	5	Fibre Cement sheet material containing white (Chrysotile), grey/brown (Amosite) and blue (Crocidolite) asbestos	Some damage	12 - 36 months
Government Employee Housing	237	Dwelling	Y	Internal	Infill around laundry internal (5m2)	5	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) and blue (Crocidolite) asbestos	Stable	Greater than 36 months
Government Employee Housing	237	Dwelling	Y	External	Infill to roof level front and rear (5m2)	5	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) and blue (Crocidolite) asbestos	Stable	Greater than 36 months
<b>Tiwi Island Shire Council</b> Alan Hudson - CEO Po Box 104 Darwin NT 0804 P: (08) 8970 9501 E: alan.hudson@tiwiislands.nt.gov.au	238	Dwelling	Y	External	Laundry splashback (5m2)	5	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months

**ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)**  
**REGION - TIWI ISLAND SHIRE**  
**AUDIT REPORTS - 3457/2, 3457/3**  
**SURVEY DATES - 2008, 2009**  
**REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012**

ASSET IDENTIFICATION	ACM LOCATION & DESCRIPTION					SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
<b>Tiwi Island Shire Council</b> Alan Hudson - CEO Po Box 104 Darwin NT 0804 P: (08) 8970 9501 E: alan.hudson@tiwiislands.nt.gov.au	238	Dwelling	Y	Internal	Wall lining to kitchen area (20m2)	20	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months
<b>Government Employee Housing</b>	239	Dwelling	Y	External	Eaves	25	Cement sheet	Stable	Greater than 36 months
<b>Government Employee Housing</b>	239	Dwelling	Y	External	Infill above windows	1	Cement sheet	Stable	Greater than 36 months
<b>Remote Community Housing</b>	245	Dwelling	Y	External	Ceiling lining to verandah (20m2)	20	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months
<b>Remote Community Housing</b>	245	Dwelling	Y	Internal	Ceiling lining throughout (20m2)	20	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months
<b>Catholic Diocese of Darwin</b> Andy McCracken Property Manager GPO Box 476 DARWIN NT 0801 P: (08) 8942 6000 E: property@darwin.catholic.org.au M: 0447 349 889	246	Vacant Land	N/A	Internal	No access	Unknown			

**ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)**  
**REGION - TIWI ISLAND SHIRE**  
**AUDIT REPORTS - 3457/2, 3457/3**  
**SURVEY DATES - 2008, 2009**  
**REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012**

ASSET IDENTIFICATION		ACM LOCATION & DESCRIPTION				SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
<b>Tiwi Land Council</b> Kate Hadden PO Box 38545 WINNELLIE NT 0821 P: (08) 8997 0797 E: tiwilcnrm@bigpond.com	248	Old Health clinic	Y	External	Infill above door west entrance (<1m2)	1	Fibre Cement sheet material containing white (Chrysotile), grey/brown (Amosite) and blue (Crocidolite) asbestos	Some damage	12 - 36 months
<b>Remote Community Housing</b>	258	Dwelling	N/A	Internal	No access	Unknown			
<b>Tiwi Island Shire Council</b> Alan Hudson - CEO Po Box 104 Darwin NT 0804 P: (08) 8970 9501 E: alan.hudson@tiwiislands.nt.gov.au	264	Library Building	Y	External	Ceiling lining to verandah and eaves (50m2)	50	Fibre Cement sheet material containing white (Chrysotile) asbestos	Some damage	12 - 36 months
<b>Tiwi Island Shire Council</b> Alan Hudson - CEO Po Box 104 Darwin NT 0804 P: (08) 8970 9501 E: alan.hudson@tiwiislands.nt.gov.au	264	Library Building	Y	External	Ceiling lining to front porch (2m2)	2	Fibre Cement sheet material containing white (Chrysotile) asbestos	Some damage	12 - 36 months
<b>Tiwi Island Shire Council</b> Alan Hudson - CEO Po Box 104 Darwin NT 0804 P: (08) 8970 9501 E: alan.hudson@tiwiislands.nt.gov.au	264	Library Building	N/A	Internal	No access	Unknown			
<b>Remote Community Housing</b>	265	Dwelling	N/A	Internal	No access	Unknown			



ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)  
 REGION - TIWI ISLAND SHIRE  
 AUDIT REPORTS - 3457/2, 3457/3  
 SURVEY DATES - 2008, 2009  
 REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012

ASSET IDENTIFICATION	ACM LOCATION & DESCRIPTION					SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
Remote Community Housing	272	Dwelling	Y	External	Eaves and internal ceiling lining (150m <sup>2</sup> )	150	Fibre Cement sheet material containing white (Chrysotile) asbestos	Some damage	12 - 36 months
Remote Community Housing	275	Dwelling	Y	Internal	Upper infill panels in corridor (2m <sup>2</sup> )	2	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months
Remote Community Housing	290	Dwelling	Y	External	Wall lining to ground floor room (30m <sup>2</sup> )	30	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Some damage	12 - 36 months
Remote Community Housing	290	Dwelling	Y	External	Wall lining main house (30m <sup>2</sup> )	30	Fibre Cement sheet material containing white (Chrysotile) asbestos	Some damage	12 - 36 months
Remote Community Housing	290	Dwelling	Y	External	Electrical backing board	1	Area accessed but not sampled. Based on findings in similar areas, it is highly likely the resin backing board contains asbestos	Stable	Greater than 36 months
Remote Community Housing	290	Dwelling	Y	Internal	Wall lining throughout (210m <sup>2</sup> )	210	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months

ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)  
 REGION - TIWI ISLAND SHIRE  
 AUDIT REPORTS - 3457/2, 3457/3  
 SURVEY DATES - 2008, 2009  
 REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012

ASSET IDENTIFICATION		ACM LOCATION & DESCRIPTION				SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
Department of Education and Training	292	Pre-School Building	Y	Internal	South Classroom walls	35	Cement sheet	Stable	Greater than 36 months
Department of Education and Training	292	Pre-School Building	Y	Internal	South Classroom ceiling	50	Cement sheet	Stable	Greater than 36 months
Department of Education and Training	292	Pre-School Building	Y	Internal	North Classroom Shower Partitions	5	Cement sheet	Stable	Greater than 36 months
Department of Education and Training	292	Pre-School Building	Y	Internal	North Classroom ceiling	75	Cement sheet	Stable	Greater than 36 months
Department of Education and Training	292	Pre-School Building	Y	Internal	Northern classroom toilet walls excluding west wall	20	Cement sheet	Stable	Greater than 36 months
Department of Education and Training	293	School Block D	Y	External	Verandah decking	18	Cement sheet	Some damage	12 - 36 months
Department of Education and Training	293	School Block D	Y	External	Classroom walls-external	45	Cement sheet	Some damage	12 - 36 months
Department of Education and Training	293	School Block D	Y	External	Verandah ceiling lining	18	Cement sheet	Stable	Greater than 36 months
Department of Education and Training	293	School Block D	Y	Internal	Classroom wall	45	Cement sheet	Stable	Greater than 36 months

**ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)**  
**REGION - TIWI ISLAND SHIRE**  
**AUDIT REPORTS - 3457/2, 3457/3**  
**SURVEY DATES - 2008, 2009**  
**REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012**

ASSET IDENTIFICATION		ACM LOCATION & DESCRIPTION				SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
Department of Education and Training	293	School Block D	Y	Internal	Classroom ceiling	50	Cement sheet	Stable	Greater than 36 months
Department of Education and Training	293	School Block E	Y	External	Classroom external walls	45	Cement sheet	Stable	Greater than 36 months
Department of Education and Training	293	School Block E	Y	Internal	Classroom wall	45	Cement sheet	Stable	Greater than 36 months
Department of Education and Training	293	School Block E	Y	Internal	Classroom ceiling	50	Cement sheet	Stable	Greater than 36 months
<b>Tiwi Island Shire Council</b> Alan Hudson - CEO Po Box 104 Darwin NT 0804 P: (08) 8970 9501 E: alan.hudson@tiwiislands.nt.gov.au	295	Single Men's Quarters/Contractors Quarters	Y	External	Infill adjacent front door	1	Fibre Cement sheet material containing white (Chrysotile), grey/brown (Amosite) and blue (Crocidolite)	Some damage	12 - 36 months
<b>Government Employee Housing</b>	296	Dwelling	Y	Internal	Wall lining to bathroom and laundry (25m2)	25	Fibre Cement sheet material containing white (Chrysotile) asbestos	Some damage	12 - 36 months
<b>Government Employee Housing</b>	296	Dwelling	Y	Internal	Ceiling lining throughout (100m2)	100	Fibre Cement sheet material containing white (Chrysotile) asbestos	Stable	Greater than 36 months

**ASBESTOS REGISTER - 56. MILIKAPITI (SNAKE BAY)**  
**REGION - TIWI ISLAND SHIRE**  
**AUDIT REPORTS - 3457/2, 3457/3**  
**SURVEY DATES - 2008, 2009**  
**REGISTER ISSUE DATE - WEDNESDAY 7 NOVEMBER 2012**

ASSET IDENTIFICATION		ACM LOCATION & DESCRIPTION				SURVEY RESULTS 2008/09			
RESPONSIBLE ENTITY	LOT NUMBER	ASSET TYPE	ACM (Y/N)	LOCATION	DESCRIPTION	QTY	MATERIAL TYPE	MATERIAL CONDITION	RISK RATING & REMOVAL MANAGEMENT TIMELINE
Remote Community Housing	306	Units 1, 2, 3, 4	Y	External	Ceiling lining to front and rear porch (7m2)	7	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months
Remote Community Housing	306	Units 1, 2, 3, 4	Y	Internal	Partition to shower (4m2)	4	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months
Remote Community Housing	306	Units 1, 2, 3, 4	Y	Internal	Ceiling lining throughout (45m2)	45	Fibre Cement sheet material containing white (Chrysotile) and grey/brown (Amosite) asbestos	Stable	Greater than 36 months
<b>Tiwi Island Shire Council</b> Alan Hudson - CEO Po Box 104 Darwin NT 0804 P: (08) 8970 9501 E: alan.hudson@tiwiislands.nt.gov.au	312	Vacant Lot	Y	Grounds	Vertical flange gasket	<1	Gasket	Stable	Greater than 36 months
<b>Silcar</b> Bill Reynolds Area Manager Nth QLD & NT PO Box 2217 CAIRNS QLD 4870 P: (07) 4031 3593 E: bill.reynolds@team.telstra.com	319	Receiver station	N/A	All areas	No access	Unknown			