

01/12/2016

Health Safety Environment Australia Pty Ltd

Unit 2 / 1 Steele Street

Winnellie, NT, 0802

Fred Build

Telephone + 61 8 8984 3222

Shed 3/80 Pruen Rd, Berrimah

Facsimile + 61 8 8984 4466

jason@fredbuild.com.au

www.hseaustralia.com.au

Re: Asbestos Inspection of 17 Lindsay Street (Units 1 – 4 Ground Level), Darwin City

Dear Jason,

Thank you for the opportunity to provide Fred Build with HSE Australia's Asbestos Inspection Services.

An inspection of the internal building structure to unit's one, two, three and four, on the ground level of the building was performed by me on the first day of December 2016. This was at your request, as you have clients that require certification that no asbestos exists in the above mentioned areas.

During the inspection no suspicious materials were located in any of the four units. No samples were taken from the site.

There is no reason to believe any asbestos containing material exist in the above mentioned areas. Common areas, external areas and or areas not mentioned above do not for a part of the inspection result.

Regards



Darren Kenny

Licensed Asbestos Assessor

NTWS-AA-450841