



**AEC ENVIRONMENTAL**  
MANAGING THE ENVIRONMENTAL RISKS

**ASBESTOS CLEARANCE CERTIFICATE**

Report No. 80568 - ACC

<b>DATE OF INSPECTION:</b>	Saturday 24 <sup>th</sup> October 2009
<b>TIME OF INSPECTION:</b>	15:35
<b>PROPERTY NAME/ ADDRESS:</b>	Wanguri Shopping Centre Lyons Street WANGURI Northern Territory
<b>ASBESTOS REMOVAL CONTRACTOR:</b>	McMahon Services Pty Ltd
<b>LOCATION:</b>	Vacant shop toilet/bathroom & customer area
<b>WORK UNDERTAKEN:</b>	Removal of asbestos containing wall linings to bathroom/toilet area & removal of asbestos containing ceiling panels
<b>INSPECTION NOTES:</b>	All accessible surfaces were visually inspected and found to be clear of any asbestos containing debris. However the rear wall of the toilet that is facing the adjoining tenancy still remains, along with the right hand corner section of wall lining to the Doctors surgery, the exposed edge of the sheet has been sealed to prevent contamination.

AEC Environmental hereby confirm that the asbestos removal in the location as specified above has been completed in accordance with the NOHSC Code of Practice for the Safe Removal of Asbestos.

Airborne Fibre Monitoring, together with this visual inspection, confirms that the location as specified above is fit for re-occupation (asbestos related matters only).

Inaccessible areas and areas requiring destruction or demolition have not been inspected and caution should be exercised if demolition or alterations are contemplated.

For any further information please do not hesitate to contact the undersigned on 8941 9441.

Signed

**Phillip Frey**  
Approved Counter



**AEC ENVIRONMENTAL**  
MANAGING THE ENVIRONMENTAL RISKS

**REPORT No. : 80568**

**DATE OF REPORT:** Saturday 24<sup>th</sup> October 2009

**CLIENT:** **McMahon Services**

**SUBJECT:** **Airborne Fibre Monitoring**

**PROPERTY/BLDG NAME:** **Wanguri Shopping Centre**  
**PROPERTY ADDRESS** Lyons Street  
WANGURI  
Northern Territory

**TEST METHOD:** Membrane Filter Method for the Estimation of Airborne Asbestos Dust as per AFC01.

Sample ID	Date	Monitoring Type	Time On	Run Time (min.)	Flow Rate (ml/min.)	Fibre Conc. (per ml.)
80568_1	24/10/2009	WC	11:50	234	2000	<0.01
80568_2	24/10/2009	WC	11:54	233	2000	<0.01
80568_3	24/10/2009	WC	11:56	232	2000	<0.01

**Monitoring Type Description:**

- WC- Combined working and clearance monitoring, during asbestos removal
- W- Monitoring during asbestos removal
- C- Clearance monitoring
- B- Background monitoring

**LOCATION:** Toilet/bathroom

80568\_1 Internal – Rear of adj.Deli against Adjoining wall

80568\_2 External – Adj. Front door of shop

80568\_3 External – Adj. Front window RHS of shop

Approved Counter:

**Philip Frey**  
Approved Counter.



**AEC ENVIRONMENTAL**  
MANAGING THE ENVIRONMENTAL RISKS

**REPORT No. : 80568**

**DATE OF REPORT:** Saturday 24<sup>th</sup> October 2009

**CLIENT:** **McMahon Services**

**SUBJECT:** **Airborne Fibre Monitoring**

**PROPERTY/BLDG NAME:** **Wanguri Shopping Centre**  
**PROPERTY ADDRESS** Lyons Street  
WANGURI  
Northern Territory

**TEST METHOD:** Membrane Filter Method for the Estimation of Airborne Asbestos Dust as per AFC01.

Sample ID	Date	Monitoring Type	Time On	Run Time (min.)	Flow Rate (ml/min.)	Fibre Conc. (per ml.)
80568_1	24/10/2009	WC	11:50	234	2000	<0.01
80568_2	24/10/2009	WC	11:54	233	2000	<0.01
80568_3	24/10/2009	WC	11:56	232	2000	<0.01

**Monitoring Type Description:**

WC- Combined working and clearance monitoring, during asbestos removal

W- Monitoring during asbestos removal

C- Clearance monitoring

B- Background monitoring

**LOCATION:** **Toilet/bathroom**

80568\_1 Internal – Rear of adj.Deli against Adjoining wall

80568\_2 External – Adj. Front door of shop

80568\_3 External – Adj. Front window RHS of shop

Approved Counter:

**Philip Prey**  
Approved Counter.



**AEC ENVIRONMENTAL**

MANAGING THE ENVIRONMENTAL RISKS

**REPORT No. : 80568**

**DATE OF REPORT:** Saturday 24<sup>th</sup> October 2009

**CLIENT:** **McMahon Services**

**SUBJECT:** **Airborne Fibre Monitoring**

**PROPERTY/BLDG NAME:** **Wanguri Shopping Centre**

**PROPERTY ADDRESS**  
Lyons Street  
WANGURI  
Northern Territory

**TEST METHOD:** Membrane Filter Method for the Estimation of Airborne Asbestos Dust as per AFC01.

Sample ID	Date	Monitoring Type	Time On	Run Time (min.)	Flow Rate (ml/min.)	Fibre Conc. (per ml.)
80568_1	24/10/2009	WC	11:50	234	2000	<0.01
80568_2	24/10/2009	WC	11:54	233	2000	<0.01
80568_3	24/10/2009	WC	11:56	232	2000	<0.01

**Monitoring Type Description:**

WC- *Combined working and clearance monitoring, during asbestos removal*

W- *Monitoring during asbestos removal*

C- *Clearance monitoring*

B- *Background monitoring*

**LOCATION:** **Toilet/bathroom**

80568\_1 Internal – Rear of adj.Deli against Adjoining wall

80568\_2 External – Adj. Front door of shop

80568\_3 External – Adj. Front window RHS of shop

Approved Counter:

**Phillip Prey**  
Approved Counter.

Unit 19 Star Village 32 Smith Street The Mall Darwin NT 0800

Telephone (08) 8941 9441 Fax (08) 8941 8441

P O Box 441 Darwin NT 0800

Email [aec@aecaust.com.au](mailto:aec@aecaust.com.au)

Website: [www.ae-caust.com.au](http://www.ae-caust.com.au)



**AEC ENVIRONMENTAL**  
MANAGING THE ENVIRONMENTAL RISKS

**REPORT No. : 80568**

**DATE OF REPORT:** Saturday 24<sup>th</sup> October 2009

**CLIENT:** **McMahon Services**

**SUBJECT:** **Airborne Fibre Monitoring**

**PROPERTY/BLDG NAME:** **Wanguri Shopping Centre**  
**PROPERTY ADDRESS** Lyons Street  
WANGURI  
Northern Territory

**TEST METHOD:** Membrane Filter Method for the Estimation of Airborne Asbestos Dust as per AFC01.

Sample ID	Date	Monitoring Type	Time On	Run Time (min.)	Flow Rate (ml/min.)	Fibre Conc. (per ml.)
80568_1	24/10/2009	WC	11:50	234	2000	<0.01
80568_2	24/10/2009	WC	11:54	233	2000	<0.01
80568_3	24/10/2009	WC	11:56	232	2000	<0.01

**Monitoring Type Description:**

WC- Combined working and clearance monitoring, during asbestos removal  
W- Monitoring during asbestos removal  
C- Clearance monitoring  
B- Background monitoring

**LOCATION:** **Toilet/bathroom**

80568\_1 Internal – Rear of adj.Deli against Adjoining wall

80568\_2 External – Adj. Front door of shop

80568\_3 External – Adj. Front window RHS of shop

Approved Counter:



**Philip Prey**  
Approved Counter.



**AEC ENVIRONMENTAL**  
*MANAGING THE ENVIRONMENTAL RISKS*

**ASBESTOS CLEARANCE CERTIFICATE**

Report No. 80568 - ACC

<b>DATE OF INSPECTION:</b>	<b>Saturday 24<sup>th</sup> October 2009</b>
<b>TIME OF INSPECTION:</b>	<b>15:35</b>
<b>PROPERTY NAME/ ADDRESS:</b>	<b>Wanguri Shopping Centre Lyons Street WANGURI Northern Territory</b>
<b>ASBESTOS REMOVAL CONTRACTOR:</b>	<b>McMahon Services Pty Ltd</b>
<b>LOCATION:</b>	<b>Vacant shop toilet/bathroom &amp; customer area</b>
<b>WORK UNDERTAKEN:</b>	<b>Removal of asbestos containing wall linings to bathroom/toilet area &amp; removal of asbestos containing ceiling panels</b>
<b>INSPECTION NOTES:</b>	<b>All accessible surfaces were visually inspected and found to be clear of any asbestos containing debris. However the rear wall of the toilet that is facing the adjoining tenancy still remains, along with the right hand corner section of wall lining to the Doctors surgery, the exposed edge of the sheet has been sealed to prevent contamination.</b>

AEC Environmental hereby confirm that the asbestos removal in the location as specified above has been completed in accordance with the NOHSC Code of Practice for the Safe Removal of Asbestos.

Airborne Fibre Monitoring, together with this visual inspection, confirms that the location as specified above is fit for re-occupation (asbestos related matters only).

Inaccessible areas and areas requiring destruction or demolition have not been inspected and caution should be exercised if demolition or alterations are contemplated.

For any further information please do not hesitate to contact the undersigned on 8941 9441.

Signed

**Phillip Prey**  
Approved Counter



**AEC ENVIRONMENTAL**  
MANAGING THE ENVIRONMENTAL RISKS

**ASBESTOS CLEARANCE CERTIFICATE**

Report No. 80568 - ACC

<b>DATE OF INSPECTION:</b>	Saturday 24 <sup>th</sup> October 2009
<b>TIME OF INSPECTION:</b>	15:35
<b>PROPERTY NAME/ ADDRESS:</b>	Wanguri Shopping Centre Lyons Street WANGURI Northern Territory
<b>ASBESTOS REMOVAL CONTRACTOR:</b>	McMahon Services Pty Ltd
<b>LOCATION:</b>	Vacant shop toilet/bathroom & customer area
<b>WORK UNDERTAKEN:</b>	Removal of asbestos containing wall linings to bathroom/toilet area & removal of asbestos containing ceiling panels
<b>INSPECTION NOTES:</b>	All accessible surfaces were visually inspected and found to be clear of any asbestos containing debris. However the rear wall of the toilet that is facing the adjoining tenancy still remains, along with the right hand corner section of wall lining to the Doctors surgery, the exposed edge of the sheet has been sealed to prevent contamination.

AEC Environmental hereby confirm that the asbestos removal in the location as specified above has been completed in accordance with the NOHSC Code of Practice for the Safe Removal of Asbestos.

Airborne Fibre Monitoring, together with this visual inspection, confirms that the location as specified above is fit for re-occupation (asbestos related matters only).

Inaccessible areas and areas requiring destruction or demolition have not been inspected and caution should be exercised if demolition or alterations are contemplated.

For any further information please do not hesitate to contact the undersigned on 8941 9441.

Signed

**Phillip Frey**  
Approved Counter



**AEC ENVIRONMENTAL**  
MANAGING THE ENVIRONMENTAL RISKS

**ASBESTOS CLEARANCE CERTIFICATE**

Report No. 80568 - ACC

<b>DATE OF INSPECTION:</b>	Saturday 24 <sup>th</sup> October 2009
<b>TIME OF INSPECTION:</b>	15:35
<b>PROPERTY NAME/ ADDRESS:</b>	Wanguri Shopping Centre Lyons Street WANGURI Northern Territory
<b>ASBESTOS REMOVAL CONTRACTOR:</b>	McMahon Services Pty Ltd
<b>LOCATION:</b>	Vacant shop toilet/bathroom & customer area
<b>WORK UNDERTAKEN:</b>	Removal of asbestos containing wall linings to bathroom/toilet area & removal of asbestos containing ceiling panels
<b>INSPECTION NOTES:</b>	All accessible surfaces were visually inspected and found to be clear of any asbestos containing debris. However the rear wall of the toilet that is facing the adjoining tenancy still remains, along with the right hand corner section of wall lining to the Doctors surgery, the exposed edge of the sheet has been sealed to prevent contamination.

AEC Environmental hereby confirm that the asbestos removal in the location as specified above has been completed in accordance with the NOHSC Code of Practice for the Safe Removal of Asbestos.

Airborne Fibre Monitoring, together with this visual inspection, confirms that the location as specified above is fit for re-occupation (asbestos related matters only).

Inaccessible areas and areas requiring destruction or demolition have not been inspected and caution should be exercised if demolition or alterations are contemplated.

For any further information please do not hesitate to contact the undersigned on 8941 9441.

Signed

**Phillip Prey**  
Approved Counter